

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start		Rating **	A	Issue No.	12
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_NA0019_01_s_2013_12				
Comment Code					
Inspector Comment					
The LMA has O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	13
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_NA0019_01_s_2013_13				
Comment Code					
Inspector Comment					
The LMA has adequate flood fight supplies and equipment.					

No Photos

LM Start		Rating **	A	Issue No.	14
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_NA0019_01_s_2013_14				
Comment Code					
Inspector Comment					
The LMA completed flood fight training in 2015.					

No Photos

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.01	Rating **	M	Issue No.	17
LM End	0.01	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.973111 °	39.973111 °
				-121.980466 °	-121.980466 °
DWR ID	DWR_NA0019_01_s_2013_17				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_17_20180905_00005.jpg



View of the erosion along the landside slope.

LM Start	0.41	Rating **	M	Issue No.	18
LM End	0.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.972560 °	39.972560 °
				-121.987759 °	-121.987759 °
DWR ID	DWR_NA0019_01_s_2013_18				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_18_20180905_00006.jpg



View of the erosion along the landside slope.

LM Start	0.45	Rating **	M	Issue No.	276
LM End	0.45	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.972377 °	39.972377 °
				-121.988559 °	-121.988559 °
DWR ID	DWR_NA0019_01_s_2014_276				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_276_20180905_00019.jpg



View of the erosion along the waterside slope.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.46	Rating **	M	Issue No.	19
LM End	0.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.972339 °	39.972339 °
				-121.988763 °	-121.988763 °
DWR ID	DWR_NA0019_01_s_2013_19				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_19_20180905_00007.jpg



View of the erosion along the landside slope.

LM Start	1.47	Rating **	M	Issue No.	21
LM End	1.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.969702 °	39.969702 °
				-122.006975 °	-122.006975 °
DWR ID	DWR_NA0019_01_f_2013_21				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					
Keep livestock off levee and repair damage.					

Photo 1 of 1 : FA_2018_NA0019_78_21_20180905_00009.jpg



View of the erosion caused by livestock on both slope of the levee.

LM Start	1.55	Rating **	A/W	Issue No.	42
LM End	1.58	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.969193 °	39.969052 °
				-122.008458 °	-122.008920 °
DWR ID	DWR_NA0019_01_s_2017_42				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the erosion along the water side toe.					

Photo 1 of 1 : FA_2018_NA0019_78_42_20180905_00016.jpg



View of the erosion along the waterside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.56	Rating **	A/W	Issue No.	49							
LM End		Issue Type +	Ma	Location *								
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	2017 Storm Damage		39.969250 °									
			-122.008681 °									
DWR ID	DWR_NA0019_01_s_2018_49											
Comment Code												
Inspector Comment												
Levee Evaluation Comments Description: Significant erosion on the waterside slope, 8-10 foot vertical bank for approximately 100-150'. Site ID No: 585 Site Designation: LMA-500 Repair Type: Erosion Rating: Serious Field Date: 9/6/2017 Notes: Photos from during the 2017 storm event are attached and cover all of the sites in this RD.												

No Photos

LM Start	1.67	Rating **	U	Issue No.	280							
LM End	1.67	Issue Type +	Ma	Location *								
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	DWR UCIP LMA Responsibility		39.968642 °	39.968642 °								
			-122.010494 °	-122.010494 °								
DWR ID	20770											
Comment Code												
Inspector Comment												
FS_ID: 53391 DS_ID: 20770 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/15/2018 Flap gate on WS end stuck open. Lower part of pipe is silted that makes impossible flap gate to fully close. Needs sediment cleanup around pipe outlet on WS. (O. Yakimov - DWR) 12/05/2016 Sediment buildup inside pipe (see photo) and sediment buildup on WS blocking flap gate. Crossing has been downgraded from Urgent to Non-Urgent crossing was closed on both WS and LS. (O. Magana - DWR UCIP) 10/02/2013 Flapgate blocked by soil buildup. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch steel drainage pipe through the levee, 1.5 feet below the crown. Flap gate on the waterside (WS) toe. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 509, March 1957, As-built drawings available 50-4-2394 (Station 185+40)]. FS Date: 10/15/2018 3:31:56 PM												

Photo 1 of 3 : UCIP_FA_2018_53391_78193.jpg



Open flap gate on WS end. Pipe is partially silted.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.67	Rating **	U	Issue No.	280 (cont)	
LM End	1.67	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.968642 °	39.968642 °	
				-122.010494 °	-122.010494 °	
DWR ID	20770					
Comment Code						
Inspector Comment						
FS_ID:53391 DS_ID:20770 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/15/2018 Flap gate on WS end stuck open. Lower part of pipe is silted that makes impossible flap gate to fully close. Needs sediment cleanup around pipe outlet on WS. (O.Yakimov - DWR)12/05/2016 Sediment buildup inside pipe (see photo) and sediment buildup on WS blocking flap gate. Crossing has been downgraded from Urgent to Non-Urgent crossing was closed on both WS and LS. (O. Magana - DWR UCIP)10/02/2013 Flapgate blocked by soil buildup. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch steel drainage pipe through the levee, 1.5 feet below the crown. Flap gate on the waterside (WS) toe. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 509, March 1957, As-built drawings available 50-4-2394 (Station 185+40)]. FS Date: 10/15/2018 3:31:56 PM						

Photo 2 of 3 : UCIP_FA_2018_53391_36921.jpg



Concrete headwall on LS toe.

LM Start	1.67	Rating **	U	Issue No.	280 (cont)
LM End	1.67	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_FA_2018_53391_76779.jpg



LS view of concrete headwall with wood panel blocking opening.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.77	Rating **	A	Issue No.	40
LM End	1.85	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.969528 °	39.969210 °
				-122.011982 °	-122.013383 °
DWR ID	DWR_NA0019_01_f_2018_40				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The vegetation was removed from the waterside slope.					

Photo 1 of 1 : FA_2018_NA0019_78_40_20181008_00062.jpg



View of the remove vegetation from the waterside slope.

LM Start	1.85	Rating **	M	Issue No.	32
LM End	1.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.969223 °	39.969223 °
				-122.013351 °	-122.013351 °
DWR ID	DWR_NA0019_01_f_2016_32				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.89	Rating **	U	Issue No.	282	
LM End	1.89	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.969105°	39.969105°	
				-122.014028°	-122.014028°	
DWR ID	20769					
Comment Code						
Inspector Comment						
FS_ID:53392 DS_ID:20769 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/15/2018 Flapgate on WS is missing, pipe partially blocked with silt. (O.Yakimov - DWR)12/05/2016 same as last inspection. Crossing remains "Urgent" WS opened during flood season due to damaged flap gate. (O. Magana - DWR UCIP)10/02/2013 Flapgate missing or buried on WS toe. Pipe partially blocked by soil on WS toe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 7 feet below the crown. Flap gate located on the waterside (WS) end. A 5-foot by 5-foot concrete control structure located on the landside (LS) toe. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 509, March 1957, As-built drawing no. 50-4-2394 (Station 176+10)]. FS Date: 10/15/2018 3:33:50 PM						

Photo 1 of 3 : UCIP_FA_2018_53392_78181.jpg



Partially silted pipe at WS toe missing flap gate.

LM Start	1.89	Rating **	U	Issue No.	282 (cont)
LM End	1.89	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_53392_76783.jpg



Overview of levee crown where pipe crosses.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.89	Rating **	U	Issue No.	282 (cont)	
LM End	1.89	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.969105°	39.969105°	
				-122.014028°	-122.014028°	
DWR ID	20769					
Comment Code						
Inspector Comment						
FS_ID:53392 DS_ID:20769 EP_NO: N/A Repair Type: Urgent Crossing Status: Found UCIP Comments: 10/15/2018 Flapgate on WS is missing, pipe partially blocked with silt. (O.Yakimov - DWR)12/05/2016 same as last inspection. Crossing remains "Urgent" WS opened during flood season due to damaged flap gate. (O. Magana - DWR UCIP)10/02/2013 Flapgate missing or buried on WS toe. Pipe partially blocked by soil on WS toe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 7 feet below the crown. Flap gate located on the waterside (WS) end. A 5-foot by 5-foot concrete control structure located on the landside (LS) toe. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 509, March 1957, As-built drawing no. 50-4-2394 (Station 176+10)]. FS Date: 10/15/2018 3:33:50 PM						

Photo 3 of 3 : UCIP_FA_2018_53392_76787.jpg



Damage flap gate visible on WS.

LM Start	2.53	Rating **	M	Issue No.	39
LM End	2.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.966675 °	39.966675 °
				-122.024988 °	-122.024988 °
DWR ID	DWR_NA0019_01_s_2017_39				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the erosion along the water side slope.					

Photo 1 of 1 : FA_2018_NA0019_78_39_20180905_00014.jpg



View of erosion along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	2.55	Rating **	A/W	Issue No.	46							
LM End	2.58	Issue Type +	Ma	Location *								
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	2017 Storm Damage		39.966661 °	39.966330 °								
			-122.025369 °	-122.025850 °								
DWR ID	DWR_NA0019_01_f_2017_46											
Comment Code												
Inspector Comment												
Levee Evaluation Comments Description: Site ID No:176 Site Designation:LMA-23 Repair Type: Erosion Rating:Area of Concern Field Date:6/6/2017 Notes: Problem area is not within the levee prism. The erosion exists near the crest.												

No Photos

LM Start	2.57	Rating **	M	Issue No.	283							
LM End	2.57	Issue Type +	Ma	Location *								
Category	Supplemental		GPS Latitude/Longitude									
			Start	End								
Item	DWR UCIP LMA Responsibility		39.966363 °	39.966363 °								
			-122.025755 °	-122.025755 °								
DWR ID	20877											
Comment Code												
Inspector Comment												
FS_ID:22823 DS_ID:20877 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Headwall covered with soil. Needs to be cleared at both ends. FIELD_STRUCT_DESC: 24-inch corrugated metal pipe through the levee 5-feet below the crown. Calco automatic drainage gate. Originally included in O+M manual (1957). As-built drawings available 50-4-2394. FS Date: 10/2/2013												

Photo 1 of 1 : UCIP_FA_2018_22823_38941.jpg



Concrete headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	2.75	Rating **	A/W	Issue No.	45
LM End	2.75	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2017 Storm Damage		39.964900°	39.965030°	
			-122.029000°	-122.028700°	
DWR ID	DWR_NA0019_01_f_2017_45				
Comment Code					
Inspector Comment					
Levee Evaluation Comments					
Description:					
Site ID No:271					
Site Designation:LMA-72					
Repair Type: Erosion					
Rating:Serious					
Field Date:6/6/2017					
Notes:					

No Photos

LM Start	2.76	Rating **	A/W	Issue No.	43
LM End	2.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		39.964990°	39.964763°	
			-122.028740°	-122.029082°	
DWR ID	DWR_NA0019_01_s_2017_43				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the erosion along the water side slope.					

Photo 1 of 1 : FA_2018_NA0019_78_43_20180905_00017.jpg



View of erosion along waterside toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	2.86	Rating **	M	Issue No.	284
LM End	2.86	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.963938 °	39.963938 °
				-122.030128 °	-122.030128 °
DWR ID	20767				
Comment Code					
Inspector Comment					
FS_ID:22824					
DS_ID:20767					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Pipe blocked by soil.					
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 6 feet below the crown. Flap gate on the waterside (WS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 509, March 1957, (Assumed Station 137+50) Drawing No. 50-4-2394].					
FS Date: 10/2/2013					

LM Start	2.86	Rating **	M	Issue No.	284 (cont)
LM End	2.86	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP_FA_2018_22824_38946.jpg



Flapgate blocked by soil and debris.

Photo 2 of 2 : UCIP_FA_2018_22824_38945.jpg



Flapgate blocked by soil and debris.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	2.86	Rating **	M	Issue No.	38
LM End	2.86	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.963928 °	39.963928 °
				-122.030120 °	-122.030120 °
DWR ID	DWR_NA0019_01_f_2014_38				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_38_20180905_00013.jpg



View of erosion from the cattle on both slopes.

LM Start	2.88	Rating **	M	Issue No.	20
LM End	2.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.963709°	39.963709°
				-122.030384°	-122.030384°
DWR ID	DWR_NA0019_01_s_2013_20				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_20_20180905_00008.jpg



View of the erosion along the landside slope.

LM Start	3.46	Rating **	M	Issue No.	34
LM End	3.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.946831 °	39.946831 °
				-122.051940 °	-122.051940 °
DWR ID	DWR_NA0019_01_f_2016_34				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	3.58	Rating **	M	Issue No.	35
LM End	3.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.946051 °	39.946051 °
				-122.053985 °	-122.053985 °
DWR ID	DWR_NA0019_01_f_2016_35				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_35_20180905_00011.jpg



View of the vegetation along the landside slope and toe.

LM Start	3.68	Rating **	M	Issue No.	15
LM End	3.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.945045 °	39.945045 °
				-122.053469 °	-122.053469 °
DWR ID	DWR_NA0019_01_f_2012_15				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_15_20180905_00003.jpg



View of the erosion caused by livestock along the landside slope.

LM Start	3.75	Rating **	M	Issue No.	16
LM End	3.75	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.944407 °	39.944407 °
				-122.054104 °	-122.054104 °
DWR ID	DWR_NA0019_01_f_2016_16				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_78_16_20180905_00004.jpg



View of a bush obstructing visibility.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	4.03	Rating **	A/W	Issue No.	291
LM End	4.03	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.941574 °	39.941574 °
				-122.057597 °	-122.057597 °
DWR ID	20760				

Comment Code

Inspector Comment

FS_ID:21741
DS_ID:20760
EP_NO: N/A
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments:
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5 feet below the crown. Flap gate on the waterside (WS) end. Headwalls on both sides of levee. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 509, March 1957, (Assumed Station 5+00) Drawing No. 50-4-2394].
FS Date: 10/3/2013

LM Start	4.03	Rating **	A/W	Issue No.	291 (cont)
LM End	4.03	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_21741_36937.jpg



Pipe and concrete headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_21741_36936.jpg



Flapgate on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	4.03	Rating **	A/W	Issue No.	291 (cont)	
LM End	4.03	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.941574 °	39.941574 °	
				-122.057597 °	-122.057597 °	
DWR ID	20760					
Comment Code						
Inspector Comment						
FS_ID:21741						
DS_ID:20760						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5 feet below the crown. Flap gate on the waterside (WS) end. Headwalls on both sides of levee. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 509, March 1957, (Assumed Station 5+00) Drawing No. 50-4-2394].						
FS Date: 10/3/2013						

Photo 3 of 3 : UCIP_FA_2018_21741_36935.jpg



Flapgate and concrete headwall on WS toe.

LM Start	4.11	Rating **	U	Issue No.	292	
LM End	4.11	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.940933 °	39.940933 °	
				-122.058894 °	-122.058894 °	
DWR ID	20762					
Comment Code						
Inspector Comment						
FS_ID:53395						
DS_ID:20762						
EP_NO: N/A						
Repair Type: Urgent						
Crossing Status: Found						
UCIP Comments: 10/15/2018 Missing flap gate at WS end of the pipe.						
Pipe is partially blocked with silt. Updated coordinates and CLM.						
(O.Yakimov - DWR)12/05/2016 unable to complete inspection --						
unable to locate. (O. Magana - DWR UCIP)10/03/2013 Gate missing						
from WS toe. (W. Wylie - DWR UCIP)						
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe						
through the levee, 5.5 feet below the crown. Flap gate located on the						
waterside (WS) end. Concrete headwall located on the landside (LS)						
toe. [Additional Reference(s): DWR Levee Log, 1992. USACE						
Sacramento O&M Manual Unit 509, March 1957, As-built drawing no.						
50-4-2394 (Station 0+65)].						
FS Date: 10/15/2018 3:37:24 PM						

Photo 1 of 3 : UCIP_FA_2018_53395_36942.jpg



Inlet on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Deer Creek	Left	4.22	10/02/2018 10/02/2018	Bob Duffey

LM Start	4.11	Rating **	U	Issue No.	292 (cont)	
LM End	4.11	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.940933 °	39.940933 °	
				-122.058894 °	-122.058894 °	
DWR ID	20762					
Comment Code						
Inspector Comment						
FS_ID:53395						
DS_ID:20762						
EP_NO: N/A						
Repair Type: Urgent						
Crossing Status: Found						
UCIP Comments: 10/15/2018 Missing flap gate at WS end of the pipe.						
Pipe is partially blocked with silt. Updated coordinates and CLM.						
(O.Yakimov - DWR)12/05/2016 unable to complete inspection --						
unable to locate. (O. Magana - DWR UCIP)10/03/2013 Gate missing						
from WS toe. (W. Wylie - DWR UCIP)						
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe						
through the levee, 5.5 feet below the crown. Flap gate located on the						
waterside (WS) end. Concrete headwall located on the landside (LS)						
toe. [Additional Reference(s): DWR Levee Log, 1992. USACE						
Sacramento O&M Manual Unit 509, March 1957, As-built drawing no.						
50-4-2394 (Station 0+65)].						
FS Date: 10/15/2018 3:37:24 PM						

Photo 2 of 3 : UCIP_FA_2018_53395_36941.jpg



Concrete headwall at inlet on LS toe.

LM Start	4.11	Rating **	U	Issue No.	292 (cont)
LM End	4.11	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_FA_2018_53395_78187.jpg



Concrete headwall at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Tehama County Flood Control and Water Conservation District

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Deer Creek	Right	1.89	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.68	Rating **	M	Issue No.	21
LM End	0.68	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			39.968818 °	39.968818 °
				-122.020904 °	-122.020904 °
DWR ID	20771				
Comment Code					
Inspector Comment					
FS_ID:51442 DS_ID:20771 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/05/2016 Crossing has been downgraded from Urgent to Non-Urgent some debris blocking proper function of flapgate on WS. Recommend clearing debris from WS for flapgate to function properly. (O. Magana - DWR UCIP)10/01/2013 Debris blocking proper function of flapgate on WS toe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch steel drainage pipe through the levee, 8.3 feet below the crown. Flap gate located on the waterside (WS) end. Concrete headwall located on the landside (LS). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 509, March 1957, Unit 510, April 1963, Unit 511, May 1973, Unit 512, March 1964, Unit 513, December 1970, As-builts drawing 50-4-2394 (Station 155+40)]. FS Date: 12/5/2016					

Photo 1 of 3 : UCIP_FA_2018_51442_36902.jpg



Concrete headwall at LS toe.

LM Start	0.68	Rating **	M	Issue No.	21 (cont)
LM End	0.68	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_51442_36901.jpg



Concrete headwall at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Deer Creek	Right	1.89	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.68	Rating **	M	Issue No.	21 (cont)	
LM End	0.68	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			39.968818 °	39.968818 °	
				-122.020904 °	-122.020904 °	
DWR ID	20771					
Comment Code						
Inspector Comment						
FS_ID:51442 DS_ID:20771 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/05/2016 Crossing has been downgraded from Urgent to Non-Urgent some debris blocking proper function of flapgate on WS. Recommend clearing debris from WS for flapgate to function properly. (O. Magana - DWR UCIP)10/01/2013 Debris blocking proper function of flapgate on WS toe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 24-inch steel drainage pipe through the levee, 8.3 feet below the crown. Flap gate located on the waterside (WS) end. Concrete headwall located on the landside (LS). [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual Unit 509, March 1957, Unit 510, April 1963, Unit 511, May 1973, Unit 512, March 1964, Unit 513, December 1970, As-builts drawing 50-4-2394 (Station 155+40)]. FS Date: 12/5/2016						

Photo 3 of 3 : UCIP_FA_2018_51442_36900.jpg



Outlet on WS toe.

LM Start	0.79	Rating **	A	Issue No.	19
LM End	1.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.968679 °	39.964525 °
				-122.022938 °	-122.031142 °
DWR ID	DWR_NA0019_02_f_2017_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The vegetation was removed from the landside slopes.					

Photo 1 of 1 : FA_2018_NA0019_79_19_20181008_00016.jpg



View of no vegetation along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Deer Creek	Right	1.89	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.81	Rating **	M	Issue No.	12
LM End	0.85	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.968530 °	39.968248 °
				-122.023305 °	-122.023900 °
DWR ID	DWR_NA0019_02_s_2017_12				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the crown roadway.					

Photo 1 of 1 : FA_2018_NA0019_79_12_20180905_00005.jpg



View of the erosion on the crown roadway.

LM Start	0.81	Rating **	M	Issue No.	17
LM End	0.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.968530 °	39.968248 °
				-122.023305 °	-122.023900 °
DWR ID	DWR_NA0019_02_s_2017_17				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the erosion along the landside slope.					

Photo 1 of 1 : FA_2018_NA0019_79_17_20180905_00008.jpg



View of the erosion along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Deer Creek	Right	1.89	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.82	Rating **	A/W	Issue No.	18	
LM End	0.83	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	2017 Storm Damage			39.968560 °	39.968400 °	
				-122.023400 °	-122.023600 °	
DWR ID	DWR_NA0019_02_f_2017_18					
Comment Code						
Inspector Comment						
Levee Evaluation Comments						
Description:						
Site ID No:177						
Site Designation:LMA-24						
Repair Type: Erosion						
Rating:Area of Concern						
Field Date:6/6/2017						
Notes: No real problem in concern to erosion is visible, the problem was this site had overtopping during 2017 storms. Solution would be to raise levee crest or any other form of raising the levee. Sandbags were present.						

No Photos

LM Start	0.85	Rating **	M	Issue No.	1
LM End	0.90	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			39.968165 °	39.967766 °
				-122.023828 °	-122.024620 °
DWR ID	DWR_ST0010_02_f_2022_14				
Comment Code					
Inspector Comment					
2017 Site ID: DEC 0.9 R					
Status: Eroding					
2017 Field Notes: No observed change.					
Site History: 2006 - Banks are composed of lithified cobble alluvial soils (relict alluvial fan deposits). Slow erosion of lithified lower bank materials with faster erosion of overlying less cohesive soils resulting in channel "skating" across lithified horizon. 2011 - The Deer Creek Watershed Conservation Group is planning a reach-wide repair for Deer Creek.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.25	Rating **	A/W	Issue No.	917
LM End	0.25	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051604 °	40.051604 °
				-122.184431 °	-122.184431 °
DWR ID	20775				
Comment Code					
Inspector Comment					
FS_ID:21795 DS_ID:20775 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.26) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_21795_37074.jpg



Concrete U-shaped headwall on LS toe.

LM Start	0.25	Rating **	A/W	Issue No.	917 (cont)
LM End	0.25	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_21795_37073.jpg



Concrete U-shaped headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.25	Rating **	A/W	Issue No.	917 (cont)
LM End	0.25	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051604 °	40.051604 °
				-122.184431 °	-122.184431 °
DWR ID	20775				
Comment Code					
Inspector Comment					
FS_ID:21795 DS_ID:20775 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.26) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 3 of 3 : UCIP_FA_2018_21795_37072.jpg



Concrete U-shaped headwall on WS toe.

LM Start	0.38	Rating **	A/W	Issue No.	918	
LM End	0.38	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.051572 °		40.051572 °
				-122.182093 °		-122.182093 °
DWR ID	20776					
Comment Code						
Inspector Comment						
FS_ID:22826 DS_ID:20776 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4.5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.39) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 1 of 3 : UCIP_FA_2018_22826_38961.jpg



Concrete U-shaped headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.38	Rating **	A/W	Issue No.	918 (cont)	
LM End	0.38	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.051572 °		40.051572 °
				-122.182093 °		-122.182093 °
DWR ID	20776					
Comment Code						
Inspector Comment						
FS_ID:22826 DS_ID:20776 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4.5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.39) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 2 of 3 : UCIP_FA_2018_22826_38960.jpg



Concrete U-shaped headwall on LS toe.

LM Start	0.38	Rating **	A/W	Issue No.	918 (cont)
LM End	0.38	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_FA_2018_22826_38963.jpg



Concrete U-shaped headwall with concrete swale on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.51	Rating **	A/W	Issue No.	919
LM End	0.51	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051211 °	40.051211 °
				-122.179663 °	-122.179663 °
DWR ID	20777				
Comment Code					
Inspector Comment					
FS_ID:21793					
DS_ID:20777					
EP_NO: N/A					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments:					
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.52) Drawing No. 50-4-3622].					
FS Date: 10/3/2013					

LM Start	0.51	Rating **	A/W	Issue No.	919 (cont)
LM End	0.51	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_21793_37069.jpg



Concrete U-shaped headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_21793_37068.jpg



Concrete U-shaped headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.51	Rating **	A/W	Issue No.	919 (cont)	
LM End	0.51	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.051211 °		40.051211 °
				-122.179663 °		-122.179663 °
DWR ID	20777					
Comment Code						
Inspector Comment						
FS_ID:21793 DS_ID:20777 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.52) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 3 of 3 : UCIP_FA_2018_21793_37067.jpg



Concrete U-shaped headwall and flapgate on WS toe.

LM Start	0.64	Rating **	A/W	Issue No.	920
LM End	0.64	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051699 °	40.051699 °
				-122.177320 °	-122.177320 °
DWR ID	20778				
Comment Code					
Inspector Comment					
FS_ID:21792 DS_ID:20778 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 1 of 2: 36-inch corrugated metal drainage pipe through the levee, 8.6 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.65) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_21792_37065.jpg



Concrete U-shaped headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.64	Rating **	A/W	Issue No.	920 (cont)	
LM End	0.64	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			40.051699 °	40.051699 °	
				-122.177320 °	-122.177320 °	
DWR ID	20778					
Comment Code						
Inspector Comment						
FS_ID:21792						
DS_ID:20778						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 1 of 2: 36-inch corrugated metal drainage pipe through the levee, 8.6 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.65) Drawing No. 50-4-3622].						
FS Date: 10/3/2013						

Photo 2 of 3 : UCIP_FA_2018_21792_37064.jpg



Concrete U-shaped headwall on WS toe.

LM Start	0.64	Rating **	A/W	Issue No.	920 (cont)
LM End	0.64	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_FA_2018_21792_37063.jpg



Concrete U-shaped headwall and flapgate on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.64	Rating **	M	Issue No.	921
LM End	0.64	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051702 °	40.051702 °
				-122.177308 °	-122.177308 °
DWR ID	20880				
Comment Code					
Inspector Comment					
FS_ID:51443 DS_ID:20880 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/05/2016 Crossing has been downgraded from Urgent to Non-Urgent vegetation found on WS but does not appear to prevent proper function of flap gate. Recommend clearing dry vegetation on WS above concrete headwall.(O. Magana - DWR UCIP)10/03/2013 Flapgate operation hindered by soil and vegetation on WS toe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 2 of 2: 36-inch corrugated metal drainage pipe through levee, 8.6 feet below crown. Flap gate and concrete "U" headwall located on the waterside (WS) end. Concrete "U" headwall located on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual, Unit 510, April 1963, As-built drawing No. 50-4-3622 (HLM 0.65)] FS Date: 12/5/2016					

LM Start	0.64	Rating **	M	Issue No.	921 (cont)
LM End	0.64	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_51443_37061.jpg



Concrete U-shaped headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_51443_37060.jpg



Concrete U-shaped headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.64	Rating **	M	Issue No.	921 (cont)	
LM End	0.64	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			40.051702 °	40.051702 °	
				-122.177308 °	-122.177308 °	
DWR ID	20880					
Comment Code						
Inspector Comment						
FS_ID:51443 DS_ID:20880 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 12/05/2016 Crossing has been downgraded from Urgent to Non-Urgent vegetation found on WS but does not appear to prevent proper function of flap gate. Recommend clearing dry vegetation on WS above concrete headwall.(O. Magana - DWR UCIP)10/03/2013 Flapgate operation hindered by soil and vegetation on WS toe. (W. Wylie - DWR UCIP) FIELD_STRUCT_DESC: 2 of 2: 36-inch corrugated metal drainage pipe through levee, 8.6 feet below crown. Flap gate and concrete "U" headwall located on the waterside (WS) end. Concrete "U" headwall located on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual, Unit 510, April 1963, As-built drawing No. 50-4-3622 (HLM 0.65)] FS Date: 12/5/2016						

Photo 3 of 3 : UCIP_FA_2018_51443_37059.jpg



Concrete U-shaped headwall and flapgate on WS toe.

LM Start	0.73	Rating **	M	Issue No.	13
LM End	0.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			40.052003 °	40.052003 °
				-122.175687 °	-122.175687 °
DWR ID	DWR_NA0019_04_f_2016_13				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_13_20180905_00008.jpg



View of a tree with overhanging branches.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.75	Rating **	A/W	Issue No.	922
LM End	0.75	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.052194 °	40.052194 °
				-122.175390 °	-122.175390 °
DWR ID	20779				
Comment Code					
Inspector Comment					
FS_ID:21790 DS_ID:20779 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.8 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.76) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

LM Start	0.75	Rating **	A/W	Issue No.	922 (cont)
LM End	0.75	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_21790_37057.jpg



Concrete U-shaped headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_21790_37056.jpg



Concrete U-shaped headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.75	Rating **	A/W	Issue No.	922 (cont)
LM End	0.75	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.052194 °	40.052194 °
				-122.175390 °	-122.175390 °
DWR ID	20779				
Comment Code					
Inspector Comment					
FS_ID:21790 DS_ID:20779 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.8 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.76) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 3 of 3 : UCIP_FA_2018_21790_37055.jpg



Concrete U-shaped headwall on LS toe.

LM Start	0.91	Rating **	A/W	Issue No.	923
LM End	0.91	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.053401 °	40.053401 °
				-122.172848 °	-122.172848 °
DWR ID	20780				
Comment Code					
Inspector Comment					
FS_ID:22827 DS_ID:20780 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4.5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.93) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_22827_38970.jpg



Concrete U-shaped headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.91	Rating **	A/W	Issue No.	923 (cont)
LM End	0.91	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.053401 °	40.053401 °
				-122.172848 °	-122.172848 °
DWR ID	20780				
Comment Code					
Inspector Comment					
FS_ID:22827 DS_ID:20780 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4.5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.93) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

LM Start	0.91	Rating **	A/W	Issue No.	923 (cont)
LM End	0.91	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_22827_38969.jpg



Concrete U-shaped headwall on WS toe.

Photo 3 of 3 : UCIP_FA_2018_22827_38972.jpg



Flapgate on headwall at WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.92	Rating **	M	Issue No.	50
LM End	0.92	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.053420 °	40.053420 °
				-122.172617 °	-122.172617 °
DWR ID	DWR_NA0019_04_f_2017_50				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree from the waterside toe.					

Photo 1 of 1 : FA_2018_NA0019_81_50_20180905_00022.jpg



View of the tree along waterside toe.

LM Start	1.07	Rating **	A/W	Issue No.	924
LM End	1.07	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.052400 °	40.052400 °
				-122.170279 °	-122.170279 °
DWR ID	20790				
Comment Code					
Inspector Comment					
FS_ID:21788 DS_ID:20790 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.10) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_21788_37050.jpg



Concrete U-shaped headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.07	Rating **	A/W	Issue No.	924 (cont)
LM End	1.07	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.052400 °	40.052400 °
				-122.170279 °	-122.170279 °
DWR ID	20790				
Comment Code					
Inspector Comment					
FS_ID:21788 DS_ID:20790 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.10) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

LM Start	1.07	Rating **	A/W	Issue No.	924 (cont)
LM End	1.07	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_21788_37053.jpg



Concrete U-shaped headwall and flapgate on WS toe.

Photo 3 of 3 : UCIP_FA_2018_21788_37052.jpg



Concrete U-shaped headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.11	Rating **	A/W	Issue No.	925
LM End	1.11	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051958 °	40.051958 °
				-122.170031 °	-122.170031 °
DWR ID	20773				
Comment Code					
Inspector Comment					
FS_ID:21786 DS_ID:20773 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.1 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.12) Drawing No. 50-4-3622]. FS Date: 10/3/2013					


LM Start	1.11	Rating **	A/W	Issue No.	925 (cont)
LM End	1.11	Issue Type +	Ma	Location *	

Photo 1 of 2 : UCIP_FA_2018_21786_37048.jpg



Concrete U-shaped headwall and flapgate on WS slope.

Photo 2 of 2 : UCIP_FA_2018_21786_37047.jpg



Concrete U-shaped headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.12	Rating **	M	Issue No.	27
LM End	1.12	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.051950 °	40.051950 °
				-122.169872 °	-122.169872 °
DWR ID	DWR_NA0019_04_f_2016_27				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_27_20180905_00015.jpg



View of the slope instability caused by vehicles.

LM Start	1.15	Rating **	M	Issue No.	51
LM End	1.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			40.051848 °	40.051848 °
				-122.169295 °	-122.169295 °
DWR ID	DWR_NA0019_04_f_2017_51				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : FA_2018_NA0019_81_51_20180905_00023.jpg



View of the rodent holes along the landside slope.

LM Start	1.26	Rating **	M	Issue No.	48
LM End	1.26	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.051722 °	40.051722 °
				-122.167327 °	-122.167327 °
DWR ID	DWR_NA0019_04_f_2018_48				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree limb from the crown roadway.					

Photo 1 of 1 : FA_2018_NA0019_81_48_20181008_00079.jpg



View of the tree limb that is fallen on the crown roadway.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.30	Rating **	A/W	Issue No.	926
LM End	1.30	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051563 °	40.051563 °
				-122.166630 °	-122.166630 °
DWR ID	20782				
Comment Code					
Inspector Comment					
FS_ID:21778 DS_ID:20782 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4.5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.30) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

LM Start	1.30	Rating **	A/W	Issue No.	926 (cont)
LM End	1.30	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_21778_37037.jpg



Concrete U-shaped headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_21778_37036.jpg



Concrete U-shaped headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.30	Rating **	A/W	Issue No.	926 (cont)
LM End	1.30	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051563 °	40.051563 °
				-122.166630 °	-122.166630 °
DWR ID	20782				
Comment Code					
Inspector Comment					
FS_ID:21778					
DS_ID:20782					
EP_NO: N/A					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments:					
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 4.5 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.30) Drawing No. 50-4-3622].					
FS Date: 10/3/2013					

Photo 3 of 3 : UCIP_FA_2018_21778_37035.jpg



Concrete U-shaped headwall on LS toe.

LM Start	1.39	Rating **	M	Issue No.	16
LM End	1.39	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.051493 °	40.051493 °
				-122.164935 °	-122.164935 °
DWR ID	DWR_NA0019_04_f_2014_16				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_16_20180905_00011.jpg



View of the slope instability caused by vehicles along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.39	Rating **	M	Issue No.	28
LM End	1.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.051521°	40.051521°	
			-122.164877°	-122.164877°	
DWR ID	DWR_NA0019_04_f_2016_28				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	1.43	Rating **	A/W	Issue No.	49
LM End	1.49	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	2017 Storm Damage		40.051596°	40.051979°	
			-122.164179°	-122.163106°	
DWR ID	DWR_NA0019_04_f_2017_49				
Comment Code					
Inspector Comment					
Levee Evaluation Comments Description: Site ID No:179 Site Designation:DWR_NA0019_04_s_2012_9 Repair Type: Erosion Rating:Serious Field Date:6/6/2017 Notes: Rip rap armors the river bank (appears placed in recent years). The erosion scarp is 10' below the berm at a vertical angle.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.43	Rating **	A/W	Issue No.	5
LM End	1.49	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			40.051596 °	40.051979 °
				-122.164179 °	-122.163106 °
DWR ID	DWR_ST0010_02_f_2022_15				
Comment Code					
Inspector Comment					
2017 Site ID: ELC 1.4 L					
Status: Eroding					
2017 Field Notes: A large quarry stone placed since last inspection.					
Site History: 2006 - High vertical bank due to mass failures. Thalweg meandering and erosion of bank. Banks are cohesive with non-cohesive gravel horizons. 2011 - Foundation is silty-sand with gravel.					
New slumping at the toe, mass failure continues.					

No Photos

LM Start	1.44	Rating **	M	Issue No.	29
LM End	1.44	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.051785 °	40.051785 °
				-122.164075 °	-122.164075 °
DWR ID	DWR_NA0019_04_f_2016_29				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_29_20180905_00016.jpg



View of the slope instability caused by vehicles along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.56	Rating **	A/W	Issue No.	927
LM End	1.56	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.052495 °	40.052495 °
				-122.161921 °	-122.161921 °
DWR ID	20783				
Comment Code					
Inspector Comment					
FS_ID:21776 DS_ID:20783 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.8 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.57) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

LM Start	1.56	Rating **	A/W	Issue No.	927 (cont)
LM End	1.56	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_21776_37029.jpg



Concrete U-shaped headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_21776_37028.jpg



Concrete U-shaped headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.56	Rating **	A/W	Issue No.	927 (cont)	
LM End	1.56	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.052495 °		40.052495 °
				-122.161921 °		-122.161921 °
DWR ID	20783					
Comment Code						
Inspector Comment						
FS_ID:21776						
DS_ID:20783						
EP_NO: N/A						
Repair Type: No Action Needed						
Crossing Status: Found						
UCIP Comments:						
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.8 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.57) Drawing No. 50-4-3622].						
FS Date: 10/3/2013						

Photo 3 of 3 : UCIP_FA_2018_21776_37027.jpg



Concrete U-shaped headwall on LS toe.

LM Start	1.59	Rating **	M	Issue No.	3
LM End	1.59	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.052607 °	40.052705 °
				-122.161418 °	-122.161442 °
DWR ID	DWR_NA0019_04_f_2018_3				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Tehama Co. repaired the slope that was damaged by vehicle traffic, but the damage has returned. On 4/26/16, vehicle erosion area was repaired again, but should be monitored.					

Photo 1 of 2 : FA_2018_NA0019_81_3_20180905_00003.jpg



View of a dip along the levee slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.59	Rating **	M	Issue No.	3 (cont)	
LM End	1.59	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Slope Stability			40.052607 °		40.052705 °
				-122.161418 °		-122.161442 °
DWR ID	DWR_NA0019_04_f_2018_3					
Comment Code						
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.						
Inspector Comment						
Tehama Co. repaired the slope that was damaged by vehicle traffic, but the damage has returned. On 4/26/16, vehicle erosion area was repaired again, but should be monitored.						

Photo 2 of 2 : FA_2018_NA0019_81_3_20180905_00004.jpg



View of the levee slope damaged by vehicle traffic.

LM Start	1.69	Rating **	A/W	Issue No.	928
LM End	1.69	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.053590 °	40.053590 °
				-122.159982 °	-122.159982 °
DWR ID	20786				
Comment Code					
Inspector Comment					
FS_ID:21769					
DS_ID:20786					
EP_NO: N/A					
Repair Type: No Action Needed					
Crossing Status: Found					
UCIP Comments:					
FIELD_STRUCT_DESC: 1 of 3: 36-inch corrugated metal drainage pipe through the levee, 7.3 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.70) Drawing No. 50-4-3622].					
FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_21769_37004.jpg



Concrete inlet on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.69	Rating **	A/W	Issue No.	928 (cont)	
LM End	1.69	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.053590 °		40.053590 °
				-122.159982 °		-122.159982 °
DWR ID	20786					
Comment Code						
Inspector Comment						
FS_ID:21769 DS_ID:20786 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 1 of 3: 36-inch corrugated metal drainage pipe through the levee, 7.3 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.70) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 2 of 3 : UCIP_FA_2018_21769_37003.jpg



Concrete inlet on WS toe.

LM Start	1.69	Rating **	A/W	Issue No.	928 (cont)
LM End	1.69	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_FA_2018_21769_37002.jpg



Concrete inlet on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.69	Rating **	A/W	Issue No.	929
LM End	1.69	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.053601 °	40.053601 °
				-122.159966 °	-122.159966 °
DWR ID	20883				
Comment Code					
Inspector Comment					
FS_ID:21768 DS_ID:20883 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 2 of 3: 36-inch corrugated metal drainage pipe through the levee, 7.3 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.70) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

LM Start	1.69	Rating **	A/W	Issue No.	929 (cont)
LM End	1.69	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_21768_37000.jpg



Concrete headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_21768_36999.jpg



Concrete headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.69	Rating **	A/W	Issue No.	929 (cont)
LM End	1.69	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.053601 °	40.053601 °
				-122.159966 °	-122.159966 °
DWR ID	20883				
Comment Code					
Inspector Comment					
FS_ID:21768 DS_ID:20883 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 2 of 3: 36-inch corrugated metal drainage pipe through the levee, 7.3 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.70) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 3 of 3 : UCIP_FA_2018_21768_36998.jpg



Concrete headwall on LS toe.

LM Start	1.69	Rating **	A/W	Issue No.	930
LM End	1.69	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.053614 °	40.053614 °
				-122.159956 °	-122.159956 °
DWR ID	20884				
Comment Code					
Inspector Comment					
FS_ID:21767 DS_ID:20884 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 3 of 3: 36-inch corrugated metal drainage pipe through the levee, 7.3 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.70) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_21767_36996.jpg



Concrete headwall on LS slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.69	Rating **	A/W	Issue No.	930 (cont)	
LM End	1.69	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			40.053614 °	40.053614 °	
				-122.159956 °	-122.159956 °	
DWR ID	20884					
Comment Code						
Inspector Comment						
FS_ID:21767 DS_ID:20884 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 3 of 3: 36-inch corrugated metal drainage pipe through the levee, 7.3 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 1.70) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 2 of 3 : UCIP_FA_2018_21767_36995.jpg



Concrete headwall on WS toe.

LM Start	1.69	Rating **	A/W	Issue No.	930 (cont)
LM End	1.69	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_FA_2018_21767_36994.jpg



Concrete headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.99	Rating **	A/W	Issue No.	931
LM End	1.99	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.052731 °	40.052731 °
				-122.154695 °	-122.154695 °
DWR ID	20787				
Comment Code					
Inspector Comment					
FS_ID:21766 DS_ID:20787 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 1 of 2: 36-inch corrugated metal drainage pipe through the levee, 7.6 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 2.01) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_21766_36992.jpg



Concrete headwall on LS toe.

LM Start	1.99	Rating **	A/W	Issue No.	931 (cont)
LM End	1.99	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_21766_36991.jpg



Concrete headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.99	Rating **	A/W	Issue No.	931 (cont)
LM End	1.99	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.052731 °	40.052731 °
				-122.154695 °	-122.154695 °
DWR ID	20787				
Comment Code					
Inspector Comment					
FS_ID:21766 DS_ID:20787 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 1 of 2: 36-inch corrugated metal drainage pipe through the levee, 7.6 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 2.01) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 3 of 3 : UCIP_FA_2018_21766_36990.jpg



Flapgate on WS toe.

LM Start	1.99	Rating **	A/W	Issue No.	932	
LM End	1.99	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.052729 °		40.052729 °
				-122.154673 °		-122.154673 °
DWR ID	20885					
Comment Code						
Inspector Comment						
FS_ID:22828 DS_ID:20885 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 2 of 2: 36-inch corrugated metal drainage pipe through the levee, 7.6 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 2.01) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 1 of 3 : UCIP_FA_2018_22828_38978.jpg



Concrete headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	1.99	Rating **	A/W	Issue No.	932 (cont)	
LM End	1.99	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP LMA Responsibility			40.052729 °	40.052729 °	
				-122.154673 °	-122.154673 °	
DWR ID	20885					
Comment Code						
Inspector Comment						
FS_ID:22828 DS_ID:20885 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 2 of 2: 36-inch corrugated metal drainage pipe through the levee, 7.6 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 2.01) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

LM Start	1.99	Rating **	A/W	Issue No.	932 (cont)
LM End	1.99	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_22828_38977.jpg



Concrete headwall and concrete channel on WS toe.

Photo 3 of 3 : UCIP_FA_2018_22828_38980.jpg



Flapgate on headwall at WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	2.21	Rating **	A/W	Issue No.	933
LM End	2.21	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051985°	40.051985°
				-122.150737°	-122.150737°
DWR ID	20788				
Comment Code					
Inspector Comment					
FS_ID:21763 DS_ID:20788 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.9 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 2.24) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

Photo 1 of 3 : UCIP_FA_2018_21763_36982.jpg



Concrete U-shaped headwall on WS slope.

LM Start	2.21	Rating **	A/W	Issue No.	933 (cont)
LM End	2.21	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_21763_36981.jpg



Inlet off LS toe in channel.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	2.21	Rating **	A/W	Issue No.	933 (cont)	
LM End	2.21	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.051985 °		40.051985 °
				-122.150737 °		-122.150737 °
DWR ID	20788					
Comment Code						
Inspector Comment						
FS_ID:21763 DS_ID:20788 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.9 feet below the crown. Flap gate and concrete U-shaped headwall on the waterside (WS) end. Concrete U-shaped headwall on the landside (LS) end. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 2.24) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 3 of 3 : UCIP_FA_2018_21763_36980.jpg



HDPE pipe inlet on LS toe.

LM Start	2.32	Rating **	M	Issue No.	12
LM End	2.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.052443°	40.052443°
				-122.148863°	-122.148863°
DWR ID	DWR_NA0019_04_f_2013_12				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_12_20180905_00007.jpg



View of the slope instability caused by vehicles along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	2.58	Rating **	M	Issue No.	32
LM End	2.58	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.053767°	40.053767°
				-122.144719°	-122.144719°
DWR ID	DWR_NA0019_04_f_2016_32				
Comment Code					
S2 : Repair the levee slope damaged by foot traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_32_20180905_00019.jpg



View of the slope instability caused by vehicles along the landside slope.

LM Start	2.63	Rating **	M	Issue No.	4
LM End	2.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.054352 °	40.054352 °
				-122.144245 °	-122.144245 °
DWR ID	DWR_NA0019_04_s_2012_4				
Comment Code					
DE : Debris					
Inspector Comment					

No Photos

LM Start	2.83	Rating **	M	Issue No.	916
LM End	2.86	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.055596 °	40.055985 °
				-122.141322 °	-122.141385 °
DWR ID	DWR_NA0019_04_s_2012_916				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_916_20180905_00024.jpg



View of the slope instability caused by vehicles along the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	3.01	Rating **	M	Issue No.	10
LM End	3.01	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.056388 °	40.056388 °
				-122.139168 °	-122.139168 °
DWR ID	DWR_NA0019_04_s_2012_10				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_10_20180905_00006.jpg



View of the slope instability caused by vehicles along the landside slope.

LM Start	3.02	Rating **	M	Issue No.	33
LM End	3.02	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.056388 °	40.056388 °
				-122.139003 °	-122.139003 °
DWR ID	DWR_NA0019_04_f_2016_33				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	3.04	Rating **	M	Issue No.	34
LM End	3.04	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.056353 °	40.056353 °
				-122.138656 °	-122.138656 °
DWR ID	DWR_NA0019_04_f_2016_34				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Elder Creek	Left	3.98	10/02/2018 10/02/2018	Bob Duffey

LM Start	3.09	Rating **	N	Issue No.	36
LM End	3.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			40.056825 °	40.056825 °
				-122.138088 °	-122.138088 °
DWR ID	DWR_NA0019_04_f_2016_36				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					
5 tree stumps					

No Photos

LM Start	3.13	Rating **	M	Issue No.	25
LM End	3.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.057350 °	40.057350 °
				-122.137667 °	-122.137667 °
DWR ID	DWR_NA0019_04_f_2015_25				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_81_25_20180905_00014.jpg



View of the slope instability caused by vehicles along the landside slope.

LM Start	3.29	Rating **	M	Issue No.	37
LM End	3.29	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.057685 °	40.057685 °
				-122.134770 °	-122.134770 °
DWR ID	DWR_NA0019_04_f_2016_37				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Tehama County Flood Control and Water Conservation District

No Photos

View of the blackberries along the landside slope blocking visibility and access.

No Photos

Page 36 of 36

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elder Creek	Right	3.87	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.11	Rating **	A/W	Issue No.	20
LM End	0.11	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			40.051702 °	40.051702 °
				-122.189922 °	-122.189922 °
DWR ID	20799				
Comment Code					
Inspector Comment					
FS_ID:21744 DS_ID:20799 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.4 feet below the crown. Flap gate on the waterside (WS) end. Concrete U-shaped headwalls on the WS and landside (LS) ends. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.11) Drawing No. 50-4-3622]. FS Date: 10/3/2013					

LM Start	0.11	Rating **	A/W	Issue No.	20 (cont)
LM End	0.11	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_FA_2018_21744_36945.jpg



Concrete headwall on LS toe.

Photo 2 of 3 : UCIP_FA_2018_21744_36944.jpg



Concrete headwall on LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elder Creek	Right	3.87	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.11	Rating **	A/W	Issue No.	20 (cont)	
LM End	0.11	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.051702 °	40.051702 °	
				-122.189922 °	-122.189922 °	
DWR ID	20799					
Comment Code						
Inspector Comment						
FS_ID:21744 DS_ID:20799 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.4 feet below the crown. Flap gate on the waterside (WS) end. Concrete U-shaped headwalls on the WS and landside (LS) ends. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.11) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

Photo 3 of 3 : UCIP_FA_2018_21744_36943.jpg



Concrete U-shaped headwall on WS slope.

LM Start	0.50	Rating **	M	Issue No.	21	
LM End	0.50	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.050585 °		40.050585 °
				-122.182972 °		-122.182972 °
DWR ID	20801					
Comment Code						
Inspector Comment						
FS_ID:41124						
DS_ID:20801						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Debris inside pipe at WS toe needs to be removed as it may prevent proper operation of the flapgate.						
FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.2 feet below the crown. Flap gate on the waterside (WS) end. Concrete U-shaped headwalls on the WS and landside (LS) ends. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.51) Drawing No. 50-4-3622].						
FS Date: 10/3/2013						

Photo 1 of 3 : UCIP_FA_2018_41124_36953.jpg



Concrete headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elder Creek	Right	3.87	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.50	Rating **	M	Issue No.	21 (cont)	
LM End	0.50	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			40.050585 °		40.050585 °
				-122.182972 °		-122.182972 °
DWR ID	20801					
Comment Code						
Inspector Comment						
FS_ID:41124 DS_ID:20801 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Debris inside pipe at WS toe needs to be removed as it may prevent proper operation of the flapgate. FIELD_STRUCT_DESC: 24-inch corrugated metal drainage pipe through the levee, 5.2 feet below the crown. Flap gate on the waterside (WS) end. Concrete U-shaped headwalls on the WS and landside (LS) ends. [Additional Reference(s): DWR Levee Log, 1992. USACE Sacramento O&M Manual 510, April 1963, (HLM 0.51) Drawing No. 50-4-3622]. FS Date: 10/3/2013						

LM Start	0.50	Rating **	M	Issue No.	21 (cont)
LM End	0.50	Issue Type +	Ma	Location *	

Photo 2 of 3 : UCIP_FA_2018_41124_36952.jpg



Inlet at LS toe.

Photo 3 of 3 : UCIP_FA_2018_41124_36951.jpg



Concrete headwall at LS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elder Creek	Right	3.87	10/02/2018 10/02/2018	Bob Duffey

LM Start	0.94	Rating **	M	Issue No.	8
LM End	1.05	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			40.051360 °	40.052361 °
				-122.175063 °	-122.173450 °
DWR ID	DWR_NA0019_05_f_2015_8				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Repair rodent hole on landside slope.					

Photo 1 of 1 : FA_2018_NA0019_82_8_20180905_00003.jpg



View of the rodent holes along the landside slope.

LM Start	3.01	Rating **	M	Issue No.	1
LM End	3.03	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey, DRAFT			40.054730 °	40.054970 °
				-122.140578 °	-122.140238 °
DWR ID	DWR_ST0010_02_f_2022_10				
Comment Code					
Inspector Comment					
2017 Site ID: ELC 3.0 R					
Status: Eroding					
2017 Field Notes: Does not appear to have new erosion , channel was being dredged during inspection.					
Site History: 2006 - Mass failure of this bank due to being along the outside of a bend where erosion and undercutting are the greatest. Low flow is being forced into the toe of this bank by point bar on the opposite side of the creek. 2011 - Toe of the bank continues to be undercut.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elder Creek	Right	3.87	10/02/2018 10/02/2018	Bob Duffey

LM Start	3.12	Rating **	M	Issue No.	11
LM End	3.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.055632°	40.055607°	
			-122.138910°	-122.138868°	
DWR ID	DWR_NA0019_05_s_2012_11				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	3.12	Rating **	M	Issue No.	17
LM End	3.12	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Trim / Thin Trees		40.055500°	40.055500°	
			-122.138841°	-122.138841°	
DWR ID	DWR_NA0019_05_f_2016_17				
Comment Code					
T4 : Trim trees over roadway to at least 12 feet above ground level.					
Inspector Comment					

No Photos

LM Start	3.30	Rating **	M	Issue No.	9
LM End	3.76	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		40.056831°	40.054862°	
			-122.136365°	-122.129279°	
DWR ID	DWR_NA0019_05_s_2012_9				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

*** Location**
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable
 M : Minimally Acceptable
 U : Unacceptable
 N : Not Inspected/Rated
 C : Corrected
 A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

Tehama County Flood Control and Water Conservation District

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Tehama County Flood Control and Water Conservation District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Elder Creek	Right	3.87	10/02/2018 10/02/2018	Bob Duffey

LM Start	3.76	Rating **	U	Issue No.	18
LM End	3.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			40.054829 °	40.054829 °
				-122.129329 °	-122.129329 °
DWR ID	DWR_NA0019_05_f_2016_18				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					

Photo 1 of 1 : FA_2018_NA0019_82_18_20180905_00007.jpg



View of the erosion along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---